

SOFTLINES WASTEWATER TESTING

TEST REPORT Number: TURA180101272

Date: 07/06/2018

Application no.: A000827811

Factory:

Factory's name: LTA srl

Address: Via Donatello 28/30, Campi Bisenzio, Florence, Italy, 50013

Wastewater treatment plant: On-site Wastewater Treatment Plant

Sample description:

Date of sampling: 23/05/2018

Sample type:

Sample / Wastewater After

[Transparent, composite sample at 09:00, 10:00, 11:00, 12:00, 13:00, 14:00]

Treatment

Sample / Sludge [Grey, grab sample at 13:00]

Date received/Date test started: 28/05/2018

Tests conducted:

As requested by a brand program, for details refer to attached page(s).

Summary of test results:

Test items	Result
Wastewater - Phthalates (Ortho-phthalates)	ND
Wastewater - Alkylphenol ethoxylates / Alkylphenols (APEOs/APs)	ND
Wastewater - Perfluorinated chemicals (PFCs)	ND
Wastewater - Brominated and chlorinated flame retardants / subgroup -	ND
Other flame retardants	
Wastewater - Azo dyes / subgroup - Carcinogenic dyes / subgroup -	ND
Disperse dyes	
Wastewater - Organotin compounds	ND
Wastewater - Chlorinated benzenes / subgroup - Chlorinated toluenes	ND
Wastewater - Chlorinated solvents / subgroup – other VOCs	ND
Wastewater - Chlorophenols	ND
Wastewater - Short-chained chlorinated paraffins (SCCPs)	ND
Wastewater - Heavy metals	D





SOFTLINES WASTEWATER TESTING

TEST REPORT

Number: TURA180101272

Test items	Result
Sludge - Phthalates (Ortho-phthalates)	ND
Sludge - Alkylphenol ethoxylates / Alkylphenols (APEOs/APs)	ND
Sludge - Perfluorinated chemicals (PFCs)	ND
Sludge - Brominated and chlorinated flame retardants / subgroup - Other	ND
flame retardants	
Sludge - Azo dyes / subgroup — Carcinogenic dyes / subgroup — Disperse	ND
dyes	
Sludge - Organotin compounds	ND
Sludge - Chlorinated benzenes / subgroup - Chlorinated toluenes	ND
Sludge - Chlorinated solvents / subgroup – other VOCs	ND
Sludge - Chlorophenols	ND
Sludge - Short-chained chlorinated paraffins (SCCPs)	ND
Sludge - Heavy metals	D

Note: ND = Not detected

D = Detected [please specify actual result]

= No comment

N/A = Not applicable

- = Did not perform

* = See remark

Prepared And Checked By:

Selvihan Elidüzgün Environmental Engineer

For Intertek Testing Services Turkey

Authorized By:

Zeynep Akın

Chemical Laboratory Manager For Intertek Testing Services Turkey

